

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #1. Battery sign is posted at the entrance to location

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #2 Photo at entrance of location.



Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #6 Erosion sediment moving down access road. BMP's need maintenance.



Photo #7 Erosion sediment moving down access road. BMP's need maintenance.

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #8 Erosion sediment moving down access road at entrance to location. BMP's need maintenance or are not in place.



Photo #9 Erosion sediment moving down access road at entrance . BMP's need maintenance or are not in place.

Laramie Energy LLC
API # 077-08484
Inspection # 696600461



Photo #10. Erosion moving sediment off location at the entrance to location. BMP's not in place or needs maintenance.



Photo #11. Erosion moving sediment off location at the entrance to location. BMP's needs maintenance.