

**Laramie Energy LLC**  
**API # 077-08653**  
**Inspection # 696600463**



**Photo #1. Battery sign is posted at the entrance to location**

Laramie Energy LLC  
API # 077-08653  
Inspection # 696600463



**Photo #2 Photo at entrance of location.**



**Photo #3 Photo at entrance of location.**



Laramie Energy LLC  
API # 077-08653  
Inspection # 696600463



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC  
API # 077-08653  
Inspection # 696600463



**Photo #6 Erosion sediment moving off tank berm and off location, choking out vegetation**



**Photo #7. Erosion sediment moving off tank berm and off location, choking out vegetation**



Laramie Energy LLC  
API # 077-08653  
Inspection # 696600463



**Photo #8** Erosion sediment moving off location and down access road at entrance to location. BMP's need maintenance or are not in place.



**Photo #9** Erosion sediment moving off location and down access road at entrance to location. BMP's need maintenance or are not in place.