

Laramie Energy LLC  
API # 077-08652  
Inspection # 696600465



Photo #1. Battery sign is posted at the entrance to location

Laramie Energy LLC  
API # 077-08652  
Inspection # 696600465



**Photo #2 Photo at entrance of location.**



**Photo #3 Photo at entrance of location.**

Laramie Energy LLC  
API # 077-08652  
Inspection # 696600465



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC  
API # 077-08652  
Inspection # 696600465



**Photo #6 Erosion sediment moving off access road and onto location.**



**Photo #7. Erosion sediment moving off access road and onto location.**

Laramie Energy LLC  
API # 077-08652  
Inspection # 696600465



**Photo #8 Erosion sediment moving down access road and onto location. BMP's need maintenance or are not in place.**



**Photo #9 8 Erosion sediment moving down access road and onto location. BMP's need maintenance or are not in place.**