

# *Inspection Photos*

*API#103-40008*

*Operator: Chevron*

*Inspection Number: 692401202*

*Inspection Date: 7/31/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of location to Southwest.

July 31, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Operating PA Emerald API#103-40008



**Photo#2:**  
View of emerged vegetation in seeded area.



**Photo#3:**  
View of emerged vegetation in seeded area.

July 31, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Operating PA Emerald API#103-40008