

Inspection Photos
Location Name: CSOC 697-14
Location ID: 324172
Inspection Date: July 26, 2019



Photo #1 – Aerial view of the location (GISOnline Maps).



Photo #2 – Location sign.

Inspection Photos
Location Name: CSOC 697-14
Location ID: 324172
Inspection Date: July 26, 2019



Photo #3 – Unlabeled AST located north of the well CSOC 697-14 #1.



Photo #4 – Hole in liner.



Inspection Photos
Location Name: CSOC 697-14
Location ID: 324172
Inspection Date: July 26, 2019



Photo #5 – Hole in liner.



Photo #6 – Hole in liner.

Inspection Photos
Location Name: CSOC 697-14
Location ID: 324172
Inspection Date: July 26, 2019



Photo #7 – Vegetation within secondary containment.



Photo #8 – Vegetation and sediment in the pit.

Inspection Photos
Location Name: CSOC 697-14
Location ID: 324172
Inspection Date: July 26, 2019



Photo #9 – Hole in netting.



Photo #10 – Open access gate.

