

Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #1 – View of north side of Pit Facility ID #414402 (Pond G) from NW corner.



Photo #2 – Liner patch in southern portion of west anchor trench.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #3 – Orange ratchet strap sagging into pit fluids, view from west side of pit.



Photo #4 – De minimis accumulations of road base on pit liner in SW corner of pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #5 – Liner patch in southern portion of east berm.



Photo #6 - Liner patch in southern portion of east anchor trench.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #7 – View of north end of pit from east side.



Photo #8 – Unused flowlines east of Conex boxes has been removed.



Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #9 - Overview of tank battery from NE corner of pit.



Photo #10 – Inlet in NE corner of pit has been removed and fence has been patched by operator.



Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019




Photo #11 – Localized accumulation of fluids along south side of tank battery.



Photo #12 – Localized accumulation of fluids along east side of tank battery.



Inspection Photos

Location Name: Pond G G Centralized E&P Waste Management Facility

Location ID: #324288 & Facility ID: #437578

Inspection Date: August 5, 2019



Photo #13 – Localized accumulation of fluids along west side of tank battery. Note wildlife mesh has been installed over filter sock tub in response to previous FIR.



Photo #14 – Localized accumulations of stained gravel and possible staining observed on top of east side of concrete pad beneath compressor shed located north of Cascade Creek #616-21-32 (API #045-10444) well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources