

# *Inspection Photos*

*API#103-09043*

*Operator: Eagle Operating*

*Inspection Number: 692401205*

*Inspection Date: 7/31/19*





Photo#1:  
Overview of location to East.

July 31, 2019




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Operating PA Emerald API#103-09043



Photo#2:  
View of location to West.

July 31, 2019



Photo#3:  
Plate welded to top of Well casing.



Photo#4:  
Shallow pit area remaining on site.

July 31, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Eagle Operating PA Emerald API#103-09043