

## Inspection Photos

Location Name: Trail Ridge 12-inch Produced Water Line

Spill/Release ID: 464253

Inspection Date: July 26, 2019



**Photo #1 – Aerial view of the location, the spill location is marked by the black drop (GISOnline Maps).**



**Photo #2 – View of the filled excavation looking northwest.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Trail Ridge 12-inch Produced Water Line

Spill/Release ID: 464253

Inspection Date: July 26, 2019



**Photo #3 – View of the filled excavation looking southwest.**



**Photo #4 – View of the drainage located southwest of the spill location. The southwest extent of the excavation can be seen in the upper portion of the photo. The photo was taken looking northeast.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Trail Ridge 12-inch Produced Water Line

Spill/Release ID: 464253

Inspection Date: July 26, 2019



**Photo #5 – View of the drainage looking southwest.**



**Photo #6 – View of the drainage looking southwest.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources