

Laramie Energy LLC
API # 077-08606
Inspection # 696600467



Photo #1. Battery sign is posted at the entrance to location

Laramie Energy LLC
API # 077-08606
Inspection # 696600467



Photo #2 Photo at entrance of location.

Photo #3 Photo at entrance of location.

Laramie Energy LLC
API # 077-08606
Inspection # 696600467



Photo #4 Photo of the tank battery.



Photo #5. Photo at wellheads

Laramie Energy LLC
API # 077-08606
Inspection # 696600467



Photo #6 Erosion sediment moving off location and choking out vegetation

Photo #7 Erosion sediment moving off location and choking out vegetation by tank battery.