

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #1. Battery sign is posted at the entrance to location.

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #2 Photo at entrance of location.



Photo #3 Photo at entrance of location.

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #4 Photo of tank battery.



Photo #5. Photo of wellheads

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #6 Photo of holes in tank containment liner on south side of tanks.



Photo #7 Photo of holes in tank containment liner on south side of tanks.

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #8 Photo of holes in tank containment liner on east side of tanks.



Photo #9 Photo of holes in tank containment liner on east side of tanks.

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #10 Soil stained by wellhead



Photo #11 Soil stained by wellhead

Maralex Resources Inc.
API # 077-10203
Inspection # 696600471



Photo #12 Unused equipment on location



Photo #13 Unused equipment on location