

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #1. Battery sign is posted at the entrance to location.

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #2 Photo at entrance to location



Photo #3 Photo at entrance to location

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #4. Photo of tank battery



Photo #5. Photo of wellhead signs.

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #6 Photo of stained soil or gravel inside of tank containment

Photo #7 Photo of stained soil or gravel inside of tank containment

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #8 Photo of stained soil or gravel inside of tank containment

Photo #9 Photo of stained soil or gravel inside of tank containment

Laramie Energy LLC
API # 077-08871
Inspection # 696600480




Photo #10 Photos of stained soil around 300 barrel production tanks, and oily waste or stains on the tanks.



Photo #11. Photos of stained soil around 300 barrel production, tanks and oily waste or stains on the tanks.

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #12 Photos of stained or oily waste on 300 barrel production tanks.

Photo #13. Photos of stained or oily waste on 300 barrel production tanks.

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #14 Photo of stains and thick oily waste on tank, before I scratched surface substance. Tanks are in need of cleaning.



Photo #15. Photo of stains and thick oily waste on tank, after I scratched surface. Tanks are in need of cleaning.