

Laramie Energy LLC
API # 077-08851
Inspection # 696600484



Photo #1. Battery sign is posted at the entrance to location.

Laramie Energy LLC
API # 077-08871
Inspection # 696600480



Photo #2 Photo at entrance to location



Photo #3 Photo at entrance to location

Laramie Energy LLC
API # 077-08851
Inspection # 696600484



4. Photo of tank battery



Photo #5. Photo of wellhead signs.

Laramie Energy LLC
API # 077-08851
Inspection # 696600484



Photo #6 Photo of Sediment moving off location from behind tank battery, choking out vegetation. Berm is used as a BMP has lost compaction and needs maintenance.

Photo #7 Photo of Sediment moving off location from behind tank battery, choking out vegetation.

Laramie Energy LLC
API # 077-08851
Inspection # 696600484



Photo #8 Photo of Sediment moving off location from behind tank battery, choking out vegetation. Berm is used as a BMP has lost compaction and needs maintenance.



Photo #9 Photo of Sediment moving off location from behind tank battery, choking out vegetation.