

Inspection Photos
Location Name: Peterson Ridge 01-20H
Location ID: 426365



Photo 1. Tracking of mud clods onto highway 14. 8/12/2019



Photo 2. Tracking of mud clods onto highway 14. 8/12/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Peterson Ridge 01-20H
Location ID: 426365



Photo 3. Tracking of mud clods onto highway 14. 8/12/2019



Photo 4. Tracking of mud clods onto highway 14. 8/12/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Peterson Ridge 01-20H
Location ID: 426365



Photo 5. Tracking onto highway 14. 8/13/2019



Photo 6. Tracking onto highway 14. 8/13/2019



Inspection Photos
Location Name: Peterson Ridge 01-20H
Location ID: 426365



**Photo 7. Sediment migrating off location and into ditch.
8/13/2019**



Photo 8. Close up of photo 7. 8/13/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources