

**Inspection Photos**  
**Location Name: Grizzly 3-32H**  
**Location ID: 436007**



**Photo 1. Non reportable spill at wellhead. Containment that has become trash/debris at wellhead.**



**Photo 2. Close up of photo 1.**

**Inspection Photos**  
**Location Name: Grizzly 3-32H**  
**Location ID: 436007**



**Photo 3. Non reportable spill at wellhead. Containment that has become trash/debris at wellhead.**



**Photo 4. Close up of photo 3.**

**Inspection Photos**  
**Location Name: Grizzly 3-32H**  
**Location ID: 436007**



**Photo 5. Trash/debris on location.**



**Photo 6. Trash/debris on location.**

Inspection Photos  
Location Name: Grizzly 3-32H  
Location ID: 436007



Photo 7. Equipment staging.



Photo 8. Equipment staging in interim reclamation area.

**Inspection Photos**  
**Location Name: Grizzly 3-32H**  
**Location ID: 436007**



**Photo 9. Equipment staging in interim reclamation area.**



**Photo 10. Tracking BMP on right side of photo, tracking onto highway 14 continuing to occur on left side of photo.**

**Inspection Photos**  
**Location Name: Grizzly 3-32H**  
**Location ID: 436007**



**Photo 11. Tracking continuing to occur onto highway 14.**



**Photo 12. Tracking onto highway 14.**