

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 1. Rock added to area behind cattle guard. Tracking still occurring through cattle guard and onto concrete apron.



Photo 2. Tracking occurring onto highway 14.

Inspection Photos
Location Name: Mutual 01-17H
Location ID: 324757



Photo 3. Tracking occurring onto highway 14 looking north.



Photo 4. Tracking occurring onto highway 14 looking south.