

Inspection Photos
Operator: BP America
Location/API #: 067-07005
Date: 8-12-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward.



Photo 3. View of erosional channeling and scouring within the northeastern portion of the project area.



Photo 4. View of reference area vegetation, dominated by ponderosa pine (*Pinus ponderosa*) and gambel oak (*Quercus gambelii*).