

Inspection Photos

Location Name: Mobil-66S95W

Location ID: 335287 & Spill/Release ID: 466509

Inspection Date: August 8, 2019



Photo #1 – Aerial view of the location. The black drip marks the spill location (GISOnline Maps).



Photo #2 – View of the excavation looking south. The sidewalls of the excavation were moist but there was no hydrocarbon staining observed or odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Mobil-66S95W

Location ID: 335287 & Spill/Release ID: 466509

Inspection Date: August 8, 2019



Photo #3 – View of the excavation looking north. The sidewalls of the excavation were moist but there was no hydrocarbon staining observed or odor.



Photo #4 – View of the eastern excavation sidewall looking east. The sidewalls of the excavation were moist but there was no hydrocarbon staining observed or odor.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources