

**County:** Adams

**Township:** 1S      **Range:** 67W      **Section:** 10      **QQ:** NENE

**Original Latitude/ Longitude:** 39.981159 / -104.872581

**Updated Latitude/ Longitude:** /

**Basis for Location Change:**

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                 |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA              | Date: NA        |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698507         | Date: 5/30/1990 |
|                                     | Doc #: 327446                               | Date: 9/2/1996  |
|                                     | Doc #: 685305810                            | Date: 4/8/2019  |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:           |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:           |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:           |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2543070              | Date: 3/2/1998  |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                 |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                 |
| <input type="checkbox"/>            | Other:                                      |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Removal of fiberglass produced water tank documented in 4/5/19 inspection.

#### Pit Status Review Summary:

Based on records review there is no evidence that there was a pit on location; inspection reports document a buried culvert/ buried produced water tank on location. This facility was decommissioned as part of the orphan well program April 2019. Pit status has been changed to closed.