

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/15/2019

Submitted Date:

08/15/2019

Document Number:

692602350**FIELD INSPECTION FORM**

Loc ID 303355 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252959	WELL	PR	09/09/1988	GW	125-06836	U.S.A. 5-11	PR

General Comment:Routine Inspection

Location				
Lease Road:				
Type	Access			
comment:	Sandy road through pasture			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign by unit			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Metal panels around unit, wellhead and meter shed			
Corrective Action:				Date:
Type	OTHER			
Comment:	Metal panels around VGS and meter shed for DP			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Pump Jack	# 1			
Comment:	Jensen unit			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Electric panel, telemetry equipment (at DP meter shed) and gas scrubber (disconnected, not in use)			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Electric motor			
Corrective Action:				Date:
Type: Gas Meter Run	# 2			
Comment:	1-Meter run in shed on east side of unit 1-Meter run for DP on west side of unit			
Corrective Action:				Date:

Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried next to meter shed on west side of unit		
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	252959	Type:	WELL	API Number:	125-06836	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT