

**Inspection Photos**  
**Location Name: PO&G Operating LLC, Anschutz 1-5**  
**Location ID: 05-061-06178**



**1. Tank battery from east side**



**2. Tank battery from west side**

**Inspection Photos**  
**Location Name: PO&G Operating LLC, Anschutz 1-5**  
**Location ID: 05-061-06178**



**3. Stained soil east side**



**4. Stained soil west side**

**Inspection Photos**  
**Location Name: PO&G Operating LLC, Anschutz 1-5**  
**Location ID: 05-061-06178**



**5. Oil covered water inside berm west side**



**6. Oil tank and 2 water tanks**