

Inspection Photos

Operator: Southland Royalty
Location/API #: 067-08976
Date: 8-14-2019



Photo 1. View of the eastern fill slope from the northeastern edge facing southward.



Photo 2. View of Russian knapweeds (*Rhaponticum repens*) within the northern project area.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area vegetation south of the project area.