

Inspection Photos
Operator: BP America
Location/API #: 067-08722
Date: 8-19-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of northern fill slope facing westward.



Photo 3. View of reference area vegetation facing southward.