

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402150609

Date Received:  
08/20/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Randy Madison

Phone

575-445-6706

Email

rmadison@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901032

Inspection Date: 07/19/2019

FIR Submit Date: 07/19/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ARP PRODUCTION COMPANY LLC

Company Number: 10471

Address: 425 HOUSTON STREET SUITE 300

City: FORTH WORTH State: TX Zip: 76102

LOCATION - Location ID: 309087

Location Name: VPR C-635S66W Number: 6SEnw County: LAS ANIMAS

Qtrqr: SEnw Sec: 6 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.030110 Longitude: -104.824730

FACILITY - API Number: 05-071- -00 Facility ID: 287870

Facility Name: VPR C Number: 142

Qtrqr: SEnw Sec: 6 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.030110 Longitude: -104.824730

CORRECTIVE ACTIONS:

**1** CA# 128363

Corrective Action: Comply with Rule 1003.f.  
Control noxious weeds.

Date: 07/10/2019

Response: CA COMPLETED

Date of Completion: 08/12/2019

Operator  
Comment:

The weeds have been sprayed within the lease right ways along the road and on the pad.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 128364

Corrective Action: Comply with Rule 1003.f.  
Provide a plan for ongoing weed control.

Date: 08/01/2019

Response: CA COMPLETED

Date of Completion: 08/19/2019

Operator Comment: I have attached a weed plan created by a professional located in Trinidad so he has knowlege of he weeds we are dealing with.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 128365

Corrective Action: Comply with the 1003 interim reclamation rules.  
Reseed and stabilize the cut slope.

Date: 07/17/2019

Response: CA COMPLETED

Date of Completion: 08/02/2019

Operator Comment: The slope has been cat tracked and hydro seeded. Wattles have been installed to help keep the seed from washing away

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**4** CA# 128366

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/17/2019

Response: CA COMPLETED

Date of Completion: 08/05/2019

Operator Comment: More rock checks have been installed along with an additonal culvert.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: This area has been totally redone with hydro-seeding, wattles and rock checks. We will see if any vegetation is established yet this fall otherwise it should come up in Spring of 2020

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy Madison

Signed: \_\_\_\_\_

Title: HSE Specialist

Date: 8/20/2019 1:27:50 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402150628	Wapiti Weed Plan
402150633	Photo Rocks and rip/rap
402150644	Photo Culvert's cleaned out
402150646	Photo Culverts cleaned out with little soil disturbance
402150649	Photo Culverts cleaned out.
402150655	Photo Culvert installed with rock rip/rap
402150659	Photo of Slope hydro-seeded
402150666	Photo of Slope hydro-seeded #2
402150667	Photo of Additional Rock Checks
402150669	Photo of the side of road with rock checks

Total Attach: 10 Files