

Interim Reclamation and Stormwater Inspection

August 14, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 441092

Inspection Document #: 697500472

Weld County, CO

NENW Section 26 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Rowe #01N-65W-26-8N
Location ID: 441092



Photo 1. Photo taken from the entrance of the location, facing South. Photo illustrates the Operator has recently performed Interim Reclamation activities.



Photo 2. Photo taken from the entrance of the location, facing Southeast. Photo illustrates the Operator has reduced the size of the location only needed for production operations.

Inspection Photos
Location Name: Rowe #01N-65W-26-8N
Location ID: 441092



Photo 3. Photo taken from the eastern well pad, facing North. Photo illustrates unmanaged weeds throughout the cut slope areas.

Inspection Photos
Location Name: Rowe #01N-65W-26-8N
Location ID: 441092



Photo 4. Photo taken from the eastern well pad, facing Northeast. Photo illustrates the cut slope areas have not been properly stabilized as rill erosion was observed.

Inspection Photos
Location Name: Rowe #01N-65W-26-8N
Location ID: 441092



Photo 5. Photo taken from the northern well pad, facing North. See comments under Photos 3 & 4.