

# Final Reclamation Inspection

August 14, 2019

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 317707

Inspection Document #: 697500474

Weld County, CO

CNE Section 30 T1N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ANDREWS #13  
Location ID: 317707



**Photo 1.** Photo taken from the approximate central location, facing West. Photo illustrates there is no evidence that final reclamation activities have been performed, as no desirable vegetation and bare patches were observed.

Inspection Photos  
Location Name: ANDREWS #13  
Location ID: 317707



**Photo 2.** Photo taken from the northeastern location (i.e., wellhead area), facing West. Photo illustrates unmanaged undesirable weeds and no evidence that final reclamation activities have been performed.

Inspection Photos  
Location Name: ANDREWS #13  
Location ID: 317707



**Photo 3.** Photo taken from the eastern location, facing Southwest. See comments under Photos 1 and 2.

Inspection Photos  
Location Name: ANDREWS #13  
Location ID: 317707



**Photo 4.** Photo taken from the eastern location. Photo illustrates equipment that has not been removed.