

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08655**  
**Date: 8-19-2019**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of southern fill slope facing westward.



Photo 3. View of musk thistles within the western project area.



Photo 4. View of erosional channel approximately 12 inches wide and deep within the southern project area.



Photo 5. View of bare soils and adjacent irrigation canal within the southern project area. Reference area vegetation in background is comprised of irrigated grass vegetation.