

Inspection Photos
Location Name: Kiyota 2
Location ID: 318561



Photo #1 Well head sign



Photo #2 Well head



Inspection Photos
Location Name: Kiyota 2
Location ID: 318561



Photo #3 Stained soil around 2" riser



Photo #4 Valves appear closed

Inspection Photos
Location Name: Kiyota 2
Location ID: 318561



Photo #5 Service Valves appear closed




Photo #6 Upper Service valves appear closed