

Inspection Photos
Location Name: State of Colorado AF #2
Location ID: 333132



Photo#1 Weeds growing on lease road and around location

Photo#2 Well head

Inspection Photos
Location Name: State of Colorado AF #2
Location ID: 333132



Photo#3 Weeds growing around location

Photo#4 Well head sign

Inspection Photos
Location Name: State of Colorado AF #2
Location ID: 333132



Photo#5 Weeds growing around location

Photo#6 Electrical panel appears to be turned off

Inspection Photos
Location Name: State of Colorado AF #2
Location ID: 333132



Photo# 7 Unused Equipment on location

Photo#6 Valves appear to be closed

Inspection Photos
Location Name: State of Colorado AF #2
Location ID: 333132



Photo#9 Valve appears to be closed