

Inspection Photos
Location Name : Robert G Burge #1
Location ID: 317684



Photo #1 weeds growing on lease road, irrigation water running down lease road



Photo #2 Well head sign starting to fade

Inspection Photos
Location Name : Robert G Burge #1
Location ID: 317684



Photo #3 Well head



Photo #4 Location holding water from farmer irrigating fields

Inspection Photos
Location Name : Robert G Burge #1
Location ID: 317684



Photo #3 Electrical panel, transformer, and meter box