

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2019

Submitted Date:

08/14/2019

Document Number:

690200053**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Heil, John _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Arauza, Steven		steven.arauza@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Gardner, Mike		mgardner@terraep.com	

General Comment:

On July 26, 2019, COGCC Environmental Staff (John Heil and Steven Arauza) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Spill ID 464253.

Operator reported a spill of produced water from a hole in a 12-inch water pipeline, located 1.6 miles south of the Crawford Trail Compressor Station (Doc #402024312).

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 70

Comment: Upon inspection, the excavation that was visible on April 30, 2019 (Inspection doc# 689401706) was filled and the disturbed area had appropriate BMPs. COGCC staff walked the drainage to the southwest of the spill location and did not observe any odors, staining or stressed vegetation (See photos).

Corrective Action: Operator shall visually monitor the drainage to the southwest of the spill location for any signs of stressed vegetation. If stressed vegetation is observed, report to COGCC EPS.

Date: 10/14/2019

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402143797	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908534
690200054	20190726 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4908533