

Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 1: Location



Photo 2: Tank Battery sign



Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 3: Tank Battery/weeds



Photo 4: Weeds near Barnett 1-20 wellhead

Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 5: Weeds north of separator



Photo 6: Weeds inside tank battery berm (SW side)



Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 7: Weeds inside berm (south)



Photo 8: Weeds inside berm (SE side)



Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 9: Weeds south (behind) tank battery berm



Photo 10: Weeds/Erosion to south end of location near ECD

Inspection Photos
Location Name: Barnett Pad
Location ID: 336571



Photo 11: Weeds/Erosion south of ECD



Photo 12: Erosion to east side of location (north of separator)