

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/20/2019

Submitted Date:

08/21/2019

Document Number:

696300500**FIELD INSPECTION FORM**

Loc ID 433229 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430650	NONFACILITY	CL	09/03/2013		-	Shable USX Tank Battery AB 11-3	CL

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Huge Pile of dirt on the Westside of location, see photo 1		
Corrective Action:	Comply with Rule 603.f .		Date: 09/23/2019
Type	UNUSED EQUIPMENT		
Comment:	Tubing Strings in Southeast corner of the location. See Photo 2		
Corrective Action:	Comply with Rule 603.f .		Date: 09/23/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 430650 Type: NONFACILIT API Number: - Status: CL Insp. Status: CL

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 08/14/2019 at approximately 15:34, I, Inspector Erica Petrie, conducted a Field Inspection at Noble Energy INC, Shable USX AB 11-03 Tank Battery, at Location ID #433229 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Tubing strings on the Southeast side of the location, see photo 2. Comply with Rule 603.f. Corrective Action date of 09/23/2019</p> <p>Dirt pile on the Westside of location, see photo 1. Comply with Rule 603.f. Corrective Action date of 09/23/2019</p> <p>It appears this location has had all production equipment removed and well associated with the Facility have been Plugged and Abandoned or will be Plugged and Abandoned in the future. Final reclamation has not begun on the location.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Educational Inspection.</p>	petrie	08/20/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300501	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915616