

Inspection Photos

08/20/2019

Operator: CARRIZO NIOBRARA LLC - 10439

Location ID: 405863

Weld County, CO

Aaron Trujillo

NE Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CARRIZO NIOBRARA LLC - 10439
Location ID: 405863



Photo 1: Photo taken from the northeast end of the location, facing southwest. Photo shows gravel/road base remaining on access road. Gravel does not appear to be conducive to reclamation



Photo 2: Photo taken from the location, facing southwest. Photo shows gravel/road base remaining on appears to be hindering reclamation.

Inspection Photos

Operator Name: CARRIZO NIOBRARA LLC - 10439

Location ID: 405863



Photo 3: Photo shows vegetation on location does not appear to be progressing towards reclamation requirement.



Photo 4: Photo shows gravel/road base remaining on location appears to be hindering reclamation.

Inspection Photos
Operator Name: CARRIZO NIOBRARA LLC - 10439
Location ID: 405863



Photo 5: Photo shows gravel/road base remaining on location appears to be hindering reclamation.



Photo 6: Photo taken from the location entrance. Photo shows gate/fence no longer in proper functioning condition.

Inspection Photos

Operator Name: CARRIZO NIOBRARA LLC - 10439

Location ID: 405863



Photo 7: Photo shows vegetation over the adjacent reference area.



Photo 8: Photo shows soil surface of the reference area. Photo shows gravel observed on location is not native material.