

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/21/2019

Submitted Date:

08/21/2019

Document Number:

692602419**FIELD INSPECTION FORM**

Loc ID 310911 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone          | Email                       | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg  | (970) 630-3909 | greg.jones@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 296560      | WELL | PR     | 10/13/2008  | GW         | 125-11303 | KELLER CATTLE 34-14<br>2S46W | PR          |

**General Comment:**Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective ActionL |                           | Date: |  |

Overall Good: ☒

|                      |                          |       |  |
|----------------------|--------------------------|-------|--|
| <b>Signs/Marker:</b> |                          |       |  |
| Type                 | WELLHEAD                 |       |  |
| Comment:             | Lease sign by meter shed |       |  |
| Corrective Action:   |                          | Date: |  |

|                           |       |  |  |
|---------------------------|-------|--|--|
| Emergency Contact Number: |       |  |  |
| Comment:                  |       |  |  |
| Corrective Action:        |       |  |  |
|                           | Date: |  |  |

Overall Good: ☒

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               | WELLHEAD   |       |  |
| Comment:           | Metal panels around wellhead, meter shed and VGS |       |  |
| Corrective Action: |  | Date: |  |

|                          |   |       |                 |
|--------------------------|---|-------|-----------------|
| <b>Equipment:</b>        |   |       | corrective date |
| Type: Vertical Separator | # 1   |       |                 |
| Comment:                 | Vertical gas separator 50% buried by meter shed |       |                 |
| Corrective Action:       |   | Date: |                 |
| Type: Gas Meter Run      | # 1   |       |                 |
| Comment:                 |   |       |                 |
| Corrective Action:       |   | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |                              |       |      |             |           |         |    |               |    |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 296560                       | Type: | WELL | API Number: | 125-11303 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                              |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production |       |      |             |           |         |    |               |    |
| Corrective Action:   |                              |       |      | Date:       |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT