

# Construction and Stormwater Inspection

August 19, 2019

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697500486

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Little Lady 21 /North Well Pad  
Location ID: 462908



**Photo 1.** Photo taken from the entrance of location, facing Northwest.

## Inspection Photos

Location Name: Little Lady 21 /North Well Pad

Location ID: 462908



**Photo 2.** Photo taken from the southeastern location, facing North. Photo illustrates the perimeter BMP (silt fence). Construction operations still underway.



**Photo 3.** Photo taken from the southeastern location, facing Southwest. Photo illustrates a water truck on location.

Inspection Photos  
Location Name: Little Lady 21 /North Well Pad  
Location ID: 462908



**Photo 4.** Photo taken from the northeastern location, facing West. Photo illustrates a ditch BMP.



**Photo 5.** Photo taken from the southwestern location, facing South. See comments under Photo 2 and 4.

Inspection Photos  
Location Name: Little Lady 21 /North Well Pad  
Location ID: 462908



**Photo 6.** Photo taken from the southern location, facing East. Photo illustrates the topsoil stockpile. Operator plans to reduce the side slopes, seed and straw crimp mulch.