

**Inspection Photos**  
**Location Name: Bondad 33-10 #100**  
**API: 05-067-07267**



**Stained and wet gravel beneath hammer unions on flow lines.**



**Stained and wet gravel beneath hammer unions on flow lines.**

**Inspection Photos**  
**Location Name: Bondad 33-10 #100**  
**API: 05-067-07267**



**Stained gravel beneath flanges at compressor.**



**Well head is stained and wet.**

Inspection Photos  
Location Name: Bondad 33-10 #100  
API: 05-067-07267



Concrete pad and surrounding gravel is stained and wet.



Concrete pad is stained at weep hole and surrounding gravel is stained.

Inspection Photos  
Location Name: Bondad 33-10 #100  
API: 05-067-07267



Unused equipment and supplies.



Location of spill/release point ID #466710.

**Inspection Photos**  
**Location Name: Bondad 33-10 #100**  
**API: 05-067-07267**



**Bondad 33-10 #100 location photo.**



**Bondad 33-10 #100 tank battery.**