

Inspection Photos
Location Name: Aristocrat Angus 1-4 Battery
Location ID 422974



Photo 1 – Location sign



Photo 2 – Location photo

Inspection Photos
Location Name: Aristocrat Angus 1-4 Battery
Location ID 422974



Photo 3 – Location photo



Photo 4 – Erosion occurring between tanks and separators

Inspection Photos
Location Name: Aristocrat Angus 1-4 Battery
Location ID 422974



Photo 5 – Erosion occurring between tanks and separators



Photo 6 – Erosion occurring south of tanks

Inspection Photos
Location Name: Aristocrat Angus 1-4 Battery
Location ID 422974



Photo 7 – Erosion occurring south of tanks



Photo 8 – Sediment transported across road into drainage