

Inspection Photos
Operator: BP America
Location/API #: 067-08881
Date: 8-21-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward.



Photo 3. View of houndstongue (*Cynoglossum officinale*) within the eastern fill slope.



Photo 4. View of reference area vegetation facing southward.