

Inspection Photos

API: 05-071-06408

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 8/22/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06408 | Date: 8/22/2019

Inspection Photos



Photo 1. Facing east toward the location. There is predominately weed growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06408 | Date: 8/22/2019

Inspection Photos



Photo 2. Facing northeast toward the location. Vegetation is not establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06408 | Date: 8/22/2019

Inspection Photos



Photo 3. There is predominately weed growth at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06408 | Date: 8/22/2019