

Inspection Photos


Loc#436196

Operator: URSA

Inspection Number: 692401267

Inspection Date: 7/24/19





Photo#1:
Tanks have been removed.

June 24, 2019



Photo#2:
Berm/ Dam area.



Photo#3:
Berm/Dam area.

June 24, 2019




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Burkle Cuttings Area Loc#436196



Photo#4:
Overview to Southwest.



Photo#5:
Overview to Northeast.

June 24, 2019



Inspection Photos: Ursa Burkle Cuttings Area Loc#436196



Photo#6:
Pond discharge.



Photo#7:
Receiving BMP.

June 24, 2019



Photo#8:
Erosion blanket installed.



Photo#9:
Erosion where erosion blanket not installed.

June 24, 2019



Photo#10:
Sediment migration




Photo#11:
Sediment migration.

June 24, 2019



Photo#12:
Erosion & sediment migration.



Photo#13:
Erosion & sediment migration.

June 24, 2019