

Inspection Photos

API#103-08494

Operator: Chevron

Inspection Number: 692401243

Inspection Date: 8/2/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
Overview of location to Northeast.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Fee 119X API#103-08494



Photo#2:
Area of failed vegetation.



Photo#3:
Close up of vegetation.

August 2, 2019



Photo#4:
Pieces of debris and areas of bare ground.

August 2, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chevron PA Fee 119X API#103-08494