

Inspection Photos  
Location Name: ALBERT 13-15  
API#: 05-071-06441  
INSP. #: 695101222



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN



Inspection Photos  
Location Name: ALBERT 13-15  
API#: 05-071-06441  
INSP. #: 695101222



**PHOTO 3: UNUSED EQUIPMENT STORED ON LOCATION (SUCKER RODE). REMOVE UNUSED EQUIPEMNT, COMPLY WITH RULE 603.f. CA DATE 9-23-19.**



**PHOTO 4: UNUSED EQUIPMENT, LID TO UNDERGROUND VALVE BOX IS LEANED TO THE SIDE. REMOVE OR REINSTALL UNUSED EQUIPMENT, COMPLY WITH RULE 603.f. CA DATE 9-23-19**