

Inspection Photos
Location Name: Nesssu –Kinder #16
Location ID: 333124



Photo 1 WH sign has been addressed.



Photo 2 Unused equipment: PU and MISC. parts

Inspection Photos
Location Name: Nessu –Kinder #16
Location ID: 333124



Photo 3 Unused equipment: PU and MISC parts