

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 1 WH sign and weeds

Photo 2 Electric panel: weeds in and around fencing

Inspection Photos
Location Name: Nessu-Kinder #16
Location ID: 333124



Photo 3 Weeds around PU and WH

Photo 4 Weeds around PU and WH