

Inspection Photos

Loc#438250

Operator: Sandridge

Inspection Number: 692401143

Inspection Date: 6/27/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southwest.

August 15, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Evans Loc#438250



Photo#2:
Resolution of CAs In Process.



Photo#3:
Resolution of CAs In Process.

August 15, 2019