

Inspection Photos
Location Name: Wattenberg Henry E Unit #C-1
Location ID: 318857



Photo 1 WH sign



Photo 2 PU. Weeds in and around PU

Inspection Photos
Location Name: Wattenberg Henry E Unit #C-1
Location ID: 318857



Colorado Oil and Gas Conservation Commission
Aug 27, 2019 09:40:30



Colorado Oil and Gas Conservation Commission
Aug 27, 2019 09:40:50

Photo 3 Production flow lines off WH are closed Well is SI.

Photo 4 Weeds in and around PU

Inspection Photos
Location Name: Wattenberg Henry E Unit #C-1
Location ID: 318857



Photo 5 Weeds around electric panel and around PU