

Inspection Photos
Location Name: Robert G Burge #2
Location ID: 318501



Photo 1 WH Weeds on location



Photo 2 WH sign faded not legible and weeds around PU

Inspection Photos
Location Name: Robert G Burge #2
Location ID: 318501



Photo 3 Stained soil around WH. Mechanical issue 1" valve on flow line appears to be leaking.



Photo 4 Weeds around electric panel

Inspection Photos
Location Name: Robert G Burge #2
Location ID: 318501



Photo 5 Weeds on location and around PU