

Inspection Photos

Location Name: WAGNER-67N64W /30NWSW

Location #: 310319



Colorado Oil & Gas Conservation Commission
40.54145, -104.59955, 1458.0m, 335°
05/17/2018 12:26:31

Photo #1

Wagner 30-32 (05-123-26227) Wellsite

Shut-In | SI

Weeds

from prior insp.



Colorado Oil & Gas Conservation Commission
40.54148, -104.59964, 1474.0m, 352°
08/27/2019 11:00:07 AM

Photo #2

Wagner 30-32 Wellsite

Shut-In | SI

Posted Emergency Number is NOT valid

Weeds appear mitigated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: WAGNER-67N64W /30NWSW

Location #: 310319



Photo #3

Wagner 30-32 Wellsite Access road

Weeds

from prior insp.



Photo #4

Wagner 30-32 Wellsite Access road

Weeds appear mitigated

Crops in 2-track access road

Inspection Photos
Location Name: WAGNER-67N64W /30NWSW
Location #: 310319



Photo #5
Wagner 30-32, Wilhite 30-34 Battery
Unused Equipment: Tubing



Photo #6
Wagner 30-32, Wilhite 30-34 Battery
Inactive