

Inspection Photos

Loc#447512

Operator: Sandridge

Inspection Number: 692401153

Inspection Date: 6/27/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from Entry to East.

August 15., 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512 B



Photo#2:
Reclamation work at West end.

August 15., 2019



Photo#3:
Area where further stabilization, BMPs are needed..

August 15., 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Open Range Loc#447512 B



Photo#4:
Staining at Well head areas.




Photo#5:
Staining at Well head areas.

August 15., 2019



Photo#6:
Staining at Well head areas.

August 15., 2019



Photo#7:
Staining at Well head areas.