

Inspection Photos

API: 05-041-06051

Operator: ETOCO LP

Inspection Date: 8/27/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-041-06051 | Date: 8/27/2019

Inspection Photos



Photo 1. Facing south along the access road. There may be compaction issues along the road preventing revegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-041-06051 | Date: 8/27/2019

Inspection Photos



Photo 2. Facing south toward the location.



Inspection Photos



Photo 3. The fence around the location is not maintained and cattle are getting onto the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-041-06051 | Date: 8/27/2019

Inspection Photos



Photo 4. Facing south at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-041-06051 | Date: 8/27/2019

Inspection Photos



Photo 5. Facing west at the center of the location.



Inspection Photos



Photo 6. Facing east at the center of the location.



Inspection Photos



Photo 7. Facing north at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-041-06051 | Date: 8/27/2019